## Ohio EPA - Daily Discharge Monitoring Report - Form 4500

SUBMISSION ID:

118071

071 S

STATUS:

Original

FACILITY: LOCATION: Ohio Valley Coal Co Powhatan No 6 Mine \* PERMIT NUMBER: Intersect St Rte 148 and Rd 86 STATION CODE:

STATION CODE: MONITORING PERIOD: 0IL00046\*DD

2010-07-01 To: 2010-07-31

COUNTY: DISTRICT:

ALLEDONIA, OH 43902 Belmont SEDO

REPORTING LAB:

ANALYST:
NO DISCHARGE INDICATOR: AL

PARAMETER	Total Precipitation	Flow Rate	рН	Total Sus Solid		Iron, Total (Fe)	Manganese, Total (Mn)	
PARAMETER CODE	00045	50050	00400	0053		01045	01055	
UNITS	Inches	MGD	S.U.	mg/l		ug/l	ug/l	
FREQUENCY SAMPLING TYPE	1/Day	1/Day	1/Week	1/We		1/Week	1/Week	
2010-07-01	24hr Total	24hr Total	Grab	Compo	site	Composite	Composite	
2010-07-02	···							
2010-07-03						<u> </u>		
2010-07-04				<del>                                     </del>				
2010-07-05		<del></del>		1			l	
2010-07-06								
2010-07-07								
2010-07-08						¥ ·		
2010-07-09								
2010-07-10								
2010-07-11								
2010-07-12								
2010-07-13								
2010-07-14								
2010-07-15								
2010-07-16								
2010-07-17								
2010-07-18								
2010-07-19					]			
2010-07-20								
2010-07-21				<u> </u>				
2010-07-22		<u> </u>		<u> </u>				
2010-07-23								
2010-07-24								
2010-07-25			<u></u>					·
2010-07-26								
2010-07-27								
2010-07-28				<u> </u>				
2010-07-29						- · · · · · · ·		
2010-07-30								
2010-07-31								
Minimum								
Maximum Average				-				
Count								
Name of Responsible Official or Authorized Representative	with the information su	pmitted herein and bas	ed on my inquiry of th	iose	Sig	nature of Responsible Represer	Official or Authorized stative	Submission Date/Time
Cody Mozena	individuals immediately responsible for obtaining the information. I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.  Page 1							2010-08- 12 15:08